

IVECO LD Informe de diagnóstico de vehículo

Información del vehículo

--/IVECO LD/Daily/Euro -/2/3/New Daily 2006 E.E./

VIN: --

Lectura del odómetro: 11992km

Matrícula: 6151GHW

Información del cliente

Nombre: --

Tel.: --

Información del dispositivo


Escáner: MaxiDAS DS900-BT

Versión: V2.10

Número de serie: VX2GS6C01292

Número de orden de reparación:
VX2GS6C0129220260414172207358

Sistema/s escaneado/s (3)

Sistema	Estado/DTC
MOTOR,EDC16C39-K LINE	 9
MOTOR,EDC16C39-CAN LINE	 9
CUADRO DE INSTRUMENTOS, CUADRO DE INSTRUMENTOS MARELLI - IPC	 0

DTC (18)

MOTOR,EDC16C39-K LINE (9 DTC)

DTC	Descripción	Estado
0x35F	NOx emissions threshold exceeded due to group faults: air control (long-term fault), DTC: 35f (info failure)	INTERMITENTES count:3
0x55F	Nox emissions threshold exceeded due to group faults: EGR control (long-term fault), DTC: 55f (info: long-term fault SCR system)	INTERMITENTES count:3
0x195	High boost pressure, DTC: 195	INTERMITENTES count:2
0x113	Accelerator pedal/brake pedal suspect, DTC: 113	INTERMITENTES count:1
0x225	Interrupted after-run, DTC: 225	INTERMITENTES count:1
0x1C3	Timeout in receiving tc01 CAN message, DTC: 1c3	PRESENTES count:10
0x2C9	CAN message timedate error, DTC: 2c9	PRESENTES count:10
0x3C9	CAN message hrdv error, DTC: 3c9	PRESENTES count:10

0x28B Short circuit to battery for throttle valve actuator, DTC: 28b INTERMITENTES
count:3

MOTOR,EDC16C39-CAN LINE (9 DTC)

DTC	Descripción	Estado
0x35F	NOx emissions threshold exceeded due to group faults: air control (long-term fault), DTC: 35f (info failure)	INTERMITENTES count:3
0x55F	Nox emissions threshold exceeded due to group faults: EGR control (long-term fault), DTC: 55f (info: long-term fault SCR system)	INTERMITENTES count:3
0x195	High boost pressure, DTC: 195	INTERMITENTES count:2
0x113	Accelerator pedal/brake pedal suspect, DTC: 113	INTERMITENTES count:1
0x225	Interrupted after-run, DTC: 225	INTERMITENTES count:1
0x1C3	Timeout in receiving tc01 CAN message, DTC: 1c3	PRESENTES count:10
0x2C9	CAN message timedate error, DTC: 2c9	PRESENTES count:10
0x3C9	CAN message hrdv error, DTC: 3c9	PRESENTES count:10
0x28B	Short circuit to battery for throttle valve actuator, DTC: 28b	INTERMITENTES count:3

Número informe

Nombre del cliente: _____

Técnico: _____

Fecha: _____

Nota: Guarde una copia de este informe para sus registros.