

IVECO LD Informe de diagnóstico de vehículo

Información del vehículo

--/IVECO LD/Daily/Euro -/2/3/New Daily 2006 E.E./

VIN: --

Lectura del odómetro: 13698km

Matrícula: 6140GHW

Información del cliente

Nombre: --

Tel.: --

Información del dispositivo



Escáner: MaxiDAS DS900-BT

Versión: V2.10

Número de serie: VX2GS6C01292

Número de orden de reparación:
VX2GS6C0129220260414173546200

Sistema/s escaneado/s (3)

Sistema	Estado/DTC
MOTOR,EDC16C39-K LINE	 5
MOTOR,EDC16C39-CAN LINE	 5
CUADRO DE INSTRUMENTOS, CUADRO DE INSTRUMENTOS MARELLI - IPC	 1

DTC (11)

MOTOR,EDC16C39-K LINE (5 DTC)

DTC	Descripción	Estado
0x225	Interrupted after-run, DTC: 225	INTERMITENTES count:9
0x2C9	CAN message timedate error, DTC: 2c9	PRESENTES count:40
0x1C3	Timeout in receiving tc01 CAN message, DTC: 1c3	INTERMITENTES count:29
0x28B	Short circuit to battery for throttle valve actuator, DTC: 28b	INTERMITENTES count:3
0x13F	Coolant pressure switch implausible, DTC: 13f	PRESENTES count:3

MOTOR,EDC16C39-CAN LINE (5 DTC)

DTC	Descripción	Estado
0x225	Interrupted after-run, DTC: 225	INTERMITENTES count:9
0x2C9	CAN message timedate error, DTC: 2c9	PRESENTES count:40

0x1C3	Timeout in receiving tc01 CAN message, DTC: 1c3	INTERMITENTES count:29
0x28B	Short circuit to battery for throttle valve actuator, DTC: 28b	INTERMITENTES count:3
0x13F	Coolant pressure switch implausible, DTC: 13f	PRESENTES count:3

CUADRO DE INSTRUMENTOS, CUADRO DE INSTRUMENTOS MARELLI - IPC (1 DTC)

DTC	Descripción	Estado
D602	CAN line, dashboard	INTERMITENTES

Número informe

Nombre del cliente: _____

Técnico: _____

Fecha: _____

Nota: Guarde una copia de este informe para sus registros.